

Arbor Oaks documentary update

13 October 2026 | English update to the retained map and atlas

Timer 2 zone 97 has a revised source address string. The entire reference remains uncertain and unlocated because the value 400 has not been reconciled with an official address. No lot, valve, controller or coverage location has been inferred.

Documented changes

Timer 2, row 48, zone 97, type R, Lakeside Grove: the former string 400-4378 is now 400-4378-4422. The former value is retained in the interactive map history. The ambiguous value 400 is unchanged and must not be silently corrected. The revised string is searchable, with no invented geometry or parcel assignment.

How to use the retained pages

This dated update takes precedence for the listed documentary references. All original map and atlas pages are retained as the earlier snapshot. Their printed colors, reference labels, row citations and totals are historical; use this update and the interactive map for the revised records. Other previously documented uncertainties remain in force.

Parcel geometry is unchanged. Documentary associations are not hydraulic boundaries or proof of physical controller, valve or pipe locations. Current controller programs and operating schedules have not been verified.

Source inventory

<https://docs.google.com/spreadsheets/d/1TFn18hVzYg2o7oYhIT2rjzQV2HqwL2JL/edit>

Original inventory modification: 2026-10-09T10:28:47.942Z. Read and compared on 13 October 2026. The modification timestamp alone was not treated as evidence of a data change.